

Annexure D

BUILDING SAFETY CERTIFICATE

No. 60/Camp/AE-III/24-25

Dated: 5/11/24

It is certified that the existing building Bois Sthali Academy (name of the building or premises) at Tentigaon Mathura

..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	<u>3</u> 1 Ground + 2 upper floors	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>

The building is owned/occupied by Bois Sthali Academy (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public Works department (Name of Department/ Govt.) on 5/11/24 (date of inspection) in the presence of Principal Bois Sthali Academy (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 5/11/24 for a period of 02 years in accordance with rule and subject to compliance of the specific conditions as appended.

1.

2.

3.

4.

Issued on 5/11/24 at Mathura by

5/11/24

सहायक अभियंता
निर्माण खण्ड 1 लो०नि०वि०
मथुरा।

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____

Name : Vidyaaram

Designation : Assistant Engineer

Name & Address of Department/ Office: CO-1 PWD

Mathura.